# THERMOGRAPHIC REPORT

Company




### **IDENTIFICATION**

Problem #	Location Name	Equipment
None	MCCB and contactor top of section 10	Panel 2 Package Substation

# **PROBLEM DESCRIPTION**

None

### **THERMOGRAM**



## TEMPERATURE MEASUREMENTS

Image Date	10/25/2006 1:34:28 PM
Target Temp	31.4 °C
Emissivity	1.00
Reflected Temp	OFF
WEATHER	
Air Temp	
Clar	

Air Temp	
Sky	
Wind Speed	
From	

Distance	Rated Load	Meas. Load	Percent Load

## **MAINTENANCE ACTION**

Description


None

# REPAIR PRIORITY

Subj. Rating	
Temp. Rating	

## **REINSPECTION**

Reinspected by	
Date	



### **Comments**

All normal